

m-Tri Terminal Nr.	wire color	function
28	red	Battery +12V
29	black	earth
27	brown	switched +12v
-	-	-
10	violett	oil pressure
14	white	turn right
13	yellow	turn left
12	blue	high beam
-	-	-
27	green	voltage supply speed sensor
30	orange	CAN low
31	grey	CAN high
m-Tri Terminal Nr.	wire gauge or indicator light cluster	function
7	gauge white or orange	Speed out
8	gauge yellow	Tacho out
9	gauge green	menue out
19	motosign red	turn left out
20	motosign green	high beam out
21	motosign black	neutral out
22	motosign violett	oilpressure out
23	motosign blue	turn right out
24	motosign yellow and orange	earth
26	motosign white + brown and gauge red	swicthed +12V